

CM6241/1000 lathe

Feature:

- Hardened and ground bed ways.
- 52mm spindle bore, cast iron machine stand u
- 16 speeds all geared head stock. и
- 3HP(2.4kW)three phase motor. u
- Foot brake giving rapid braking.
- Emergency stop button equipped on the front of headstock. и
- Jog button for easy gear engagement and inching spindle. и
- Open type chip pan easily to remove chips.
- Extra safety switch shuts down machine automatically for changing belt or gear for threading cutting.

ODEOLEIOATION	MODELS		
SPECIFICATION	CM6241×1000 CM6241 X 1500		
CAPACITY			
Swing over bed	410mm(16 ")		
Swing over cross slide	255mm(10 ")		
Swing in gap	580(23 ")		
Length of gap	250(10 ")		
Distance between centers	1000mm(40 ")		
Center height	20.5 "		
Width of bed	250(10 ")		
HEADSTOCK			
Spindle nose	D1-6		
Spindle bore	52mm(2 ")		
Taper of spindle bore	No.6Morse		
Range of spindle speed	16 changes 45-1800r/min		
FEEDS AND THREADS			
Max.travel of compound rest	102mm(4 ")		

Max.travel of cross slide	210mm(8-1/4 ")		
Leadscrew pitch	4T.P.I.		
Max.Section of tool	20×20mm(13/16 ")		
Longitudinal feeds range	0.05-1.7mm/rev(0.002 " -0.067 " /rev)		
Cross oeeds range	0.025-0.85mm(0.001 " -0.0335 " /rev)		
Metric threads range	39kinds 0.2-14mm		
Inch threads range	45kinds 2-72T.P.I		
Diametrical pitchesrange	21kinds 44D.P.		
Module pitches range	18kinds 0.3-3.5M.P.		
TAILSTOCK			
Dia.of tailstock sleeve	50mm(2 ")		
Travel of tailstock sleeve	120mm(4-3/4 ")		
Morse taper of tailstock sleeve	No.4 Morse		
Cross adjustock	±13mm(±1/2 ")		
MOTOR			
Power of main motor	2.8/3.3kw(3.8/4.5HP)3PH		
Power of coolant pump	0.1KW(1/8HP),3PH		
DIMENSION AND WEIGHT			
Overall dimension(L×W×H) mm	1940×850×1300	1940×850×1320	
Packing size(LxWxH)mm	2060×900×1640	2060×900×1640	
Net weight/Gross weight	1500/1750	1550/1800	
	<u> </u>		

STANDARD ACCESSORIES

- 200mm Three Jaw Chuck and Adapter
 320mm Four Jaw Chuck and Adapter
 300mm Face Plates

- Steady Rest
 Follow Rest

- 6. Thread Chasing Dial7. Mt/6/4 Sleeve and MT 4 Center
- 8. Oil Gun
- 9. One set of Wrenches
- 10. Operation Manual

SPECIAL ACCESSORIES

1. 200mm Driving plate 2. Quick change Tool Post 3. Taper Turning Attachment